

Project Location: Linn, Kansas

Project Overview: Evaluate Steel Bin

- Evaluate the structural stability of a steel bin that sustained damage during a wind storm. Visual observation was done to determine if the steel bin can be used to store grain in its current condition.

Project Services:

- Site Observation
- Visual Analysis
- Written Report

Photos:

